Instruction of Digital Temperature DT-1

With LCD display shows indoor outdoor temperature; max min value memory.

This thermometer could be installed by

1.Stand on desktop by rack on back panel

2.Stick to wall by the hole

3. Stick to iron by the magnet on back panel.

Technical Data

Temperature Range:

In: -50°C to 70°C (-58.0°F to 150°F), sampling period 10s,

Resolution 0.1°C, Accuracy ±1°C

Out: -50°C to 70°C (-58.0°F to 150°F), sampling period 10s,

Resolution 0.1°C, Accuracy ±1°C

Operation

Max Temperature: Press the key "Max",

Min Temperature: Press the key "Min",

Clear History: Press the key "Reset", device will update max/min value from

now on.